


Side view of Main Rotor Expandable Pin handle. Note cracks at the arrows radiating from the attachment pin.



Close up of slide # 1. Note stress corrosion cracking emanating from the attachment pin.